Approved For Release 2002/08/07: CIA-RDP81B00878R000100030016-6

PERSONAL COPY 1 OF 1

Fred To September 27, 1957

STATOTHR

A.J.H.

Ref: Report #143

Dear Al:

The referenced report covers the damaging of YJ57-P-31 606319 at Del Rio. You will note Al's statement that the LAC rear engine installation bracket PN JH-44 yoke had been modified to improve accessibility during engine installation. Also that this mode was not OK'd by LAC but was performed by local people. The fall severely damaged the accessory case including fuel control and intermediate case. The total labor and material cost for repair will probably exceed 10-12 thousand dollars. I think you should circularize all our boys on this and bring it to attention for their action.

STATOTHR

Regards,

J.H.G.

cc: J.K. C.C.G.

POTUMENT RID.

NO CHANGE OF STATES O

PERSONAL